

## **Technical Note TN-557**

## Instruction for adjusting the x4 multiplier in T2000 800Mhz radios.

03 March 1999

**Applicability** 

T20XX-81X-XXX (Wide Band 800Mhz band radios).

Outline

The T2000 800Mhz radios use a x4 frequency multiplier circuit to produce the 51.2Mhz required by the 2nd IF mixer. Often if the multiplier is not correctly tuned a whistling noise can be heard on either transmit or receive.

For best operation the frequency multiplier should be adjusted as described below.

## 1. Adjustment

Note

Ensure that L204 is correctly tuned for maximum RSSI before starting this procedure. (Refer to T2000 Service Manual Section 6.5 for details).

Procedure

- 1. Remove TCXO PCB from radio.
- 2. Monitor the output from TP1 with a frequency counter. Use an oscilloscope x10 probe for suitable isolation.
- 3. Adjust CV212 until a reading of 51.375Mhz is obtained on the frequency counter.
- 4. Refit the TCXO PCB and again monitor TP1. Ensure a reading of 51.2Mhz is obtained on the frequency counter.

## 2. Issuing authority

Name and position

Rob Haughey

of issuing officer MRD Mobiles Design Support

Tait Electronics Limited Telephone: +64–3–358–3399 PO Box 1645, Christchurch, New Zealand Facsimile: +64–3–358–3903