# DGAC HF Voice/RTTY system—9114 Power Supply fails to initialise after a power failure



### Introduction

The DGAC HF Voice system in Antarctica, documented in system drawing 03–00987 Issue B, includes an AC mains contactor in the AC power supply lead of the PS1000 power supply. The AC mains contactor is connected to the Input/Output (I/O) port of the 8571 Remote Control Interface via cable 08–05473–001. This enables the AC mains contactor to be switched remotely via a relay from the Codan 8570/8571 Remote Control System. This facility permits the linear amplifier to be disabled remotely.

A problem occurs after an AC mains power failure. The Codan 9114 Power Supply fails to initialise due to the low impedance of the AC mains contactor on the 12 V DC power supply line. The problem is overcome by providing switched 12 V DC power from the General Purpose (GP) port of the transceiver instead of the I/O port of the 8571 Remote Control Interface.

## **Symptom**

The Codan 9114 Power Supply fails to initialise after an AC mains power failure.

### **Action**

To ensure that the 9114 Power Supply initialises after an AC mains power failure:

Re—route the power supply line by connecting the cable provided (part number 08–05637–001) to the GP port of the transceiver (see Figure 1).



Once the power supply has been re—routed, the AC mains contactor can only be remotely switched when the transceiver is switched on.

Head Office

© 17-00194 Issue 1, January 1999

Page 1 of 2

Codan Pty Ltd ACN 007 590 605 81 Graves Street Newton South Australia 5074 Telephone +61 8 8305 0311 Facsimile +61 8 8305 0411

Codan (UK) Ltd Gostrey House Union Road Farnham, Surrey GU9 7PT United Kingdom Telephone +44 1252 717 272 Facsimile +44 1252 717 337 Codan Pty Ltd Suite 11A, 2 Hardy Street South Perth Western Australia 6151 Telephone +61 8 9368 5282 Facsimile +61 8 9368 5283 Codan Comunicaciones Ltda.

Av. 11 de Septiembre 2155, Of. 701/A
Edificio Panorámico
Providencia
Santiago, CHILE
Teléfono +56 2 373 9577
Facsímile +56 2 373 9579

Email: radcom@codan.com.au

Worldwide Web: www.codan.com.au

## **Implementation**

To re—route the power supply line from the GP port of the transceiver, a special purpose cable (part number 08–05637–001) must be connected (see Figure 1). The implementation is also shown in system drawing 03–00987 Issue C.

Six cables have been sent with this Service Bulletin. Three cables, (part number 08–05637–001) are provided for the new connection, and three cables, (part number 08–05473–001) are provided to replace the cables previously modified by the customer.




Figure 1: Wiring diagram for the AC contactor