



# Technical Note TN 596

TOP-xx21x Excel Conventional New V1.07 Firmware  
TOP Conventional New V1.10 Programming Software

2 November 1999

## 1. TOP-xx21x Excel Conventional V1.07 Firmware

**Applicability** Software changes to TOP-xx21x Excel Conventional have been made, resulting in the release of a new version of enhanced radio firmware, V1.07. This software will be used in all future productions of TOP Excel Conventional Radios.

### 1.1 New features available V1.07

Feature	Description	Impact on Customer
<b>Selcall Updates</b>		
Faster Ringing	Solves the 2 second wait when Selcall has not received all sub-sequences	For Alcatel Major
Ring only after auto-acknowledge	Selcall does not ring until auto-acknowledge is sent.	Minor
Selcall Decode after receipt of SDM	The radio is now able to decode further Selcalls after a SDM has been received.	Significant improvement
Fixed Tx Burst of Noise	Occasionally, when answering Selcall with the PTT, the radio did transmit a short burst of noise. This is now fixed.	Significant improvement for users.
CCDI Auto-acknowledge	Unit now sends auto-acknowledge message to <b>Computer Controlled Data Interface</b>	Significant for CCDI users
<b>Other Updates</b>		
Increase "low battery" warning volume	Increase in "low battery" warning volume level	Less chance to miss "low battery" alarm.
Ready for : Microphone Switching	This firmware is ready for top microphone. Allows user to switch between bottom and top microphone. <i>Radio Hardware Dependant. Wait for separate product announcement.</i>	Future feature 1Q2000
Ready for : <b>Receive Signal Tracking</b>	This firmware is ready for automatic adjustment of the receiver frequency. <i>Radio Hardware Dependant. Wait for separate product announcement.</i>	Future Feature 1Q2000

## 1.2 Compatibility of V1.07

Item	Description																										
Programming S/W	This Radio firmware requires TOP Conventional Programming Software V1.10																										
User Manuals	The new features are described in the Elan / Excel user manual : IPN 409-00410-00																										
Hardware	<table> <tbody> <tr> <td>Orca masked DSP :</td> <td>IPN 002-18932-10</td> </tr> <tr> <td>Orca OTP DSP :</td> <td>IPN 002-18937-13</td> </tr> <tr> <td>Orca PCB VHF Main Radio Board variant 03 :</td> <td>IPN 220-01401-03</td> </tr> <tr> <td>Orca PCB VHF Main Radio Board variant 04 :</td> <td>IPN 220-01401-04</td> </tr> <tr> <td>Orca PCB VHF Main Radio Board new variant :</td> <td>IPN 220-01588-03</td> </tr> <tr> <td>Orca PCB sub-UHF Main Radio Board variant 01:</td> <td>IPN 220-01503-01</td> </tr> <tr> <td>Orca PCB sub-UHF Main Radio Board variant 04:</td> <td>IPN 220-01503-04</td> </tr> <tr> <td>Orca PCB UHF Main Radio Board variant 06 :</td> <td>IPN 220-01392-06</td> </tr> <tr> <td>Orca PCB UHF Main Radio Board variant 07 :</td> <td>IPN 220-01392-07</td> </tr> <tr> <td>Orca PCB UHF Main Radio Board variant 08 :</td> <td>IPN 220-01392-08</td> </tr> <tr> <td>Orca PCB UHF Main Radio Board variant 11 :</td> <td>IPN 220-01392-11</td> </tr> <tr> <td>Orca PCB UHF Main Radio Board variant 03:</td> <td>IPN 220-01603-03</td> </tr> <tr> <td>Orca PCB 900 MHz Main Radio Board variant 02:</td> <td>IPN 220-01610-02</td> </tr> </tbody> </table>	Orca masked DSP :	IPN 002-18932-10	Orca OTP DSP :	IPN 002-18937-13	Orca PCB VHF Main Radio Board variant 03 :	IPN 220-01401-03	Orca PCB VHF Main Radio Board variant 04 :	IPN 220-01401-04	Orca PCB VHF Main Radio Board new variant :	IPN 220-01588-03	Orca PCB sub-UHF Main Radio Board variant 01:	IPN 220-01503-01	Orca PCB sub-UHF Main Radio Board variant 04:	IPN 220-01503-04	Orca PCB UHF Main Radio Board variant 06 :	IPN 220-01392-06	Orca PCB UHF Main Radio Board variant 07 :	IPN 220-01392-07	Orca PCB UHF Main Radio Board variant 08 :	IPN 220-01392-08	Orca PCB UHF Main Radio Board variant 11 :	IPN 220-01392-11	Orca PCB UHF Main Radio Board variant 03:	IPN 220-01603-03	Orca PCB 900 MHz Main Radio Board variant 02:	IPN 220-01610-02
Orca masked DSP :	IPN 002-18932-10																										
Orca OTP DSP :	IPN 002-18937-13																										
Orca PCB VHF Main Radio Board variant 03 :	IPN 220-01401-03																										
Orca PCB VHF Main Radio Board variant 04 :	IPN 220-01401-04																										
Orca PCB VHF Main Radio Board new variant :	IPN 220-01588-03																										
Orca PCB sub-UHF Main Radio Board variant 01:	IPN 220-01503-01																										
Orca PCB sub-UHF Main Radio Board variant 04:	IPN 220-01503-04																										
Orca PCB UHF Main Radio Board variant 06 :	IPN 220-01392-06																										
Orca PCB UHF Main Radio Board variant 07 :	IPN 220-01392-07																										
Orca PCB UHF Main Radio Board variant 08 :	IPN 220-01392-08																										
Orca PCB UHF Main Radio Board variant 11 :	IPN 220-01392-11																										
Orca PCB UHF Main Radio Board variant 03:	IPN 220-01603-03																										
Orca PCB 900 MHz Main Radio Board variant 02:	IPN 220-01610-02																										

## 1.3 Known issues remaining with V1.07

Issue	Description	Impact on Customer
Battery Capacity Indicator	If the radio powers down due to a flat battery during high powered transmission, when the radio is next powered up the battery indicator may still display two bars of charge.	Minor
SDM Error 24	Rx over-run system error occurs occasionally when sending SDM's from a fast PC.	Minor. Radio will auto re-set.
Occasional Display Flicker	Occasionally the display will "flicker" when transmitting or when entering data.	Does not effect the function of the radio.

## 2. TOP Conventional New V1.10 Programming Software

**Applicability** Software changes to TOP Conventional Programming Software have been made, resulting in the release of a new version of programming software, v1.10. This software is required to program TOP Excel radios with radio firmware V1.07. It is optional for all other conventional TOP radios.

### 2.1 New features available V1.10

Feature	Description	Impact on Customer
Supports TOP Excel V1.07 Radio Firmware	This programming software is required for the programming of TOP-xx21x Excel Conventional.	Essential
Display Contrast Adjustment	Allows the user to adjust the contrast of the display – via the user menu – for Eclipse radios only.	Better display
User Defined tone sets fixed.	Standard user defined tone sets will now work correctly.	NZ Police requirement
Entry of scangroups / alpha	This version allows the entry of scangroups in the “alpha” mode (as per manual & help text).	TEA & TEU requirement

### 2.2 Compatibility of V1.10

Item	Description
User Manuals	The new features are described in the manual : IPN 439-51100-01
Conventional Radio Firmware Database	Versions : 2.00, 2.01, 2.02, 2.03, 2.04 (TOP-xx21x Excel Conventional V1.07 = database version 2.04) V1.10 is backwards compatible.

### 2.3 Known issues remaining with V1.10

Issue	Description	Impact on Customer
Selcall tones between 1500 and 1700	QUID121- these tones are not allowed under “user defined selcall selection”	Very limited group of users.
Programming Timeout errors	QUID210 – Occasional asynchronous timeout error due to hitting ESC key to leave a window. Use “Done” button to quit read/write radio screen.	Irritation for radio programmers.
File saving	SCRF4373 – files are occasionally not saved to the correct directory with “SAVE”	Minor. Plan to fix in next version.

**Note to CSO's** This information is primarily of a technical nature. Use this information to fix reported problems. Distribute the firmware and the programming software as required only.

**Issuing authority** Andreas Becker  
MRD Product Sales Manager — Tait Orca Portables  
email: andreas.becker@tait.co.nz  
DDI: +64 3 358 0341