Technical Note TN-766

Missing Test Point on T201X Logic 220-01377-07

5th March 2003

Applicability

This Technical Note applies to all T201X's that use the logic board with the IPN of 220-01377-07

Information

In the M2000-00 Series II Service Manual Section 8.14, Test Point (TP) 609 is referred to in the set-up instructions for the T2000-A80. This information shows that for a T201x, a line needs to be run from the S24 connector of the -A80 board to TP609 on the logic board of the T201x.

For versions of the 220-01377-0x logic before version -06 this is a true and accurate instruction. However with the release of the -07 board, TP609 was accidentally removed. With the release of the 220-01377-08 board the Test Point was re-instated.

When adding a T2000-A80 to a T201X with an "-07" logic board the suggested work around is to solder the lead from the T2000-A80 onto S20 pin 4.

Compliance

None

CSO Instruction

CSO's – Please inform all technical staff, and dealers of this Technical Note.

Tait Electronics Limited
PO Box 1645, Christchurch, New Zealand
Telephone: +64–3–358–3399
Facsimile: +64–3–358–3903
www.taitworld.com/support

Issuing authority

Name and position of issuing officer	Paul Anderson Customer Support Engineer - Mobiles		
Confidentiality	Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.		
Distribution Level	Associate		
Document History	Original Release	5th March 2003	PRA

Tait Electronics Limited Telephone: +64–3–358–3399
PO Box 1645, Christchurch, New Zealand Facsimile: +64–3–358–3903
www.taitworld.com/support