



Technical Support

TECHNICAL NOTE

Technical Note TN-794

Firmware Upgrade for the T2040 Radio to V5.70

27th August 2003

Applicability This Technical Note applies to T2040 GPS radios

1. Introduction

Detail The last full release of T2040 Std firmware was V5.68. This has now been updated to **T2040 Std V5.70**.

Compatibility This firmware can be used with DOS Programming Software V2.77 or later.

What Has Changed? The main changes to note are:-

- Inter-prefix SDM transaction failure over non-Tait (refer TIMS 17629)
- TIMS00013142 Adjacent Channel Power too high on Key Off (refer TIMS 13142)
- TIMS00016035 Stun & revive firmware required on T2040 (refer TIMS 16035)

The new firmware will be placed in radios from **Serial Number 17242426**.

Please Note:-

The new firmware is available for download off the Technical Support website (www.taitworld.com/support).

Compliance None

CSO Instruction CSO's – Please inform all logistics, sales and technical staff of these changes

2. Issuing Authority

Name and Position of Issuing Officer Paul Anderson
Customer Support Engineer - Mobiles

Confidentiality Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.

Distribution Level Tait Only

Document History Original Release 27th August 2003 PRA