

# ATTENTION DEALERS TUNING MAY BE REQUIRED

## Models Affected:

H34GCU7100\_N  
H44GCU7100\_N

H44GCU7180\_N  
H44GCJ7190\_N

All MT1000™ UHF radios are tuned, in the factory, for operation in the upper 8 MHz of the sub-band. Radios programmed with frequencies outside the upper 8 MHz of the sub-band will require retuning.

## SUB-BAND

403-433  
438-470  
470-500  
488-512

## FACTORY TUNING

425-433  
462-470  
492-500  
504-512

If you are unable to retune the radio, take it to your local Motorola authorized service center. Failure to retune the radio will result in a significant reduction in received signal strength, thereby reducing the effective range of the radio.

Motorola and MT1000 are trademarks of Motorola, Inc.

Instruction Manual



68P81109C39-O