



Technical Note TN-780

Upgrade of T2030 Firmware to Version 3.33

7th June 2003

Applicability

This Technical Note applies to the T2030 Series II radio

Introduction

Detail

The last full release of T2030 firmware was V3.30. The T2030 firmware has now been updated to **T2030 V3.33**.

Compatibility

This firmware can be used with DOS Programming Software V1.61 or later (this includes the Trunked Programming Application (TPA) V2.13 beta). The firmware is available from www.taitworld.com/support.

What Has Changed?

The main changes to note are:-

- Emergency call setup failure if terminal is busy. (Refer TIMS 9205)
- T2030s sticking on TX when called. (Refer TIMS 9987)
- Radio units not responding to availability checks. (Refer TIMS 10371)
- Remote Reset while in SEM. (Refer TIMS 9202)
- Protection of Factory Model ID and Chassis Serial Number. Sometimes during a firmware upgrade the serial number and Factory Model ID were not re-programmed back into the radio. (Refer TIMS 13390)
- Trunk Channel Barring. This fixed a problem that would occur if the radio is programmed with DOS Pgm but read with the TPA (Refer TIMS 9277)

Compliance None unless approval is required by Network providers.

CSO Instruction CSO's – Please inform all logistics, sales and technical staff, and dealers of these changes

Issuing authority

Name and position of issuing officer Paul Anderson
Customer Support Engineer - Mobiles

Confidentiality Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.

Distribution Level Tait Only

Document History Original Release 7th June 2003 PRA