



DOCUMENT NUMBER: 17-00152  
ISSUE NUMBER: 2  
ISSUE DATE: March, 97

RELATED DOCUMENTS:  
C/R 24971

---

## **Premature Termination of Fax/Data Links with 9323/9360 Transceiver**

### **1. Symptom**

During transmission of a Fax or Data file using the Codan 9001 or 9002 modems with either a 9323 or 9360 transceiver, the established link may terminate early, before the proper completion of transmission. This has been found to occur with transceivers with operating software at Version 2.32 or earlier.

### **2. Remedy**

Upgrade the transceiver software.

The exact software and procedure will depend on the current software and the type of transceiver.

Contact Codan for details.

---

**Head Office**

Codan Pty Ltd  
ACN 007 590 605  
81 Graves Street  
Newton  
South Australia 5074  
International +61 8 8305 0311  
Facsimile +61 8 8305 0411

**E-mail:**  
HF@codan.com.au  
  
**World-wide web:**  
<http://www.codan.com.au>

Codan (UK) Ltd  
Gostrey House  
Union Road  
Farnham, Surrey GU9 7PT  
United Kingdom  
International +44 1252 717 272  
Facsimile +44 1252 717 337  
Telex 858355

Codan Pty Ltd  
Suite 11A, 2 Hardy Street  
South Perth  
Western Australia 6151  
International +61 8 9368 5282  
Facsimile +61 8 9368 5283