



DOCUMENT NUMBER: 17-00182  
ISSUE NUMBER: 1  
ISSUE DATE: February, '98

RELATED DOCUMENTS:  
C/R

---

## 9323/9360/9780 Software version 4.32

### 1. Introduction

9323/9360/9780 software 90-20523-005 version 4.32 has been released.

### 2. Problems corrected

#### 2.1 Incoming ALE link unable to be established prior to data call

Present in version 4.31.

In a system comprising a transceiver, 9001/2 modem and an 8570 Remote Control Console, the system would not allow an incoming ALE link to be established prior to a data call. This problem means that V4.31 is not suitable for this system.

#### 2.2 Manual tune sequence results in 'Tune Failed' message

Present in all previous releases of version 4.xx.

The transceiver would respond with a **Tune Failed** message when a manual tune was performed despite proof that the antenna had tuned correctly. This would only occur on certain frequencies and varied between installations. Auto-tune sequences were not affected.

### 3. Compatibility

Refer to Service Bulletin 17-00156 for full compatibility details.

This software is compatible with CICS version 2.10 and fully backward compatible with version 2.00.

---

#### Head Office

Codan Pty Ltd  
ACN 007 590 605  
81 Graves Street  
Newton  
South Australia 5074  
Telephone +61 8 8305 0311  
Facsimile +61 8 8305 0411

**E-mail:**  
radcom@codan.com.au  
  
**World-wide web:**  
<http://www.codan.com.au>

Codan (UK) Ltd  
Gostrey House  
Union Road  
Farnham, Surrey GU9 7PT  
United Kingdom  
Telephone +44 1252 717 272  
Facsimile +44 1252 717 337  
Telex 858355

Codan Pty Ltd  
Suite 11A, 2 Hardy Street  
South Perth  
Western Australia 6151  
Telephone +61 8 9368 5282  
Facsimile +61 8 9368 5283