Technical Note TN-691

Firmware Upgrade for Orca 5000 Trunked Radios to v4.09

26th October 2001

Applicability

This Technical Note applies to all trunked Orca 5000 portables (5030, 5035 and 5040).

1. Information

Why has it been released?

This firmware release v4.09 resolves the following issues in TOP Trunked Radios:

- Dialing restrictions being ignored after an unsuccessful preset call. See TIMS 2838
- Added enhancement to allow single key call back when queuing is disabled. See TIMS 2758
- System Error occurring when programming with PTT pressed. See TIMS 2765
- Group select not being activated on power up of low tier radios. See TIMS 3742
- System Error with large list of preset identities. See JOBS 1271
- Handset LED indicator inconsistency. See TIMS 1468
- Queuing disabled enhancement always exiting menu after call back. See TIMS 3949
- TOP 5035 keypad lockup problem when using keypad lock. See TIMS 3823

This TOP Trunked firmware release has been implemented from radio serial number **14130155,** job 157399, 25th October 2001.

2. Programming Requirements

What does it work with?

This Firmware is only compatible with Orca Trunked Programming Application PGM v3.2.0 or later, software.

The full version software, Tait Programming Utilities, (**TPU version 2.1**) can be downloaded from the web at www.taitworld.com/support. However, this is a 34 MB file, and is available on CD-ROM.

This provides Orca Trunked Programming Application PGM v3.1.0, and the patch to upgrade to PGM v3.2.0 can be executed from the drop down list.

3. Issuing Authority

Name and position of issuing officer

Graham Brenchley
Customer Support Engineer