

Figure 4.1 on the next page shows the locations of the 50Ω input and output test points and how to connect the test leads.




Figure 4.1 Positioning Of Test Leads