



Technical Note TN-589

Change to the T2000 Trunked Radio Model Codes

31 August 1999

Applicability

Applies to the T2030, T2035 and T2040

1. Introduction

Why Change?

The T2000 trunked radio line is limited to two hundred thousand serial numbers. Serial numbers are essential for allowing the radios to be recognised on a trunked system. We have had to start reusing the serial numbers, therefore, a method was devised to allow radios with the same serial number to work on the same system.

2. Modifications

What Changed?

To prevent contention on Trunked systems that could possibly have two radios with the same serial number, the model code has been changed from what the codes were previously. The previous model codes are as follows:

T2030 = 01
T2035 = 01
T2040 = 02

All of the T2000 trunked radios now have the new model code of **09**. This allows trunking systems to differentiate between two radios with the same serial number.

3. Issuing authority

Name and position of issuing officer

Barry Crates
Mobile Radio Customer Support