



Technical Note TN-773

Upgrade of T2035 Firmware to Version 3.55

14th May 2003

Applicability This Technical Note applies to the T2035 Series II radio

Introduction

Detail The last full release of T2035 firmware was V3.53 (refer TN-748). The T2035 firmware has now been updated to **T2035 V3.55**.

Compatibility This firmware can be used with DOS Programming Software V1.61 or later (this includes the Trunked Programming Application (TPA) V2.13 beta). The Programming Software is available from www.taitworld.com/support.

What Has Changed? The main changes to note are:-

- Adjacent Channel Power too high on Key Off. (TIMS 13145)
- T2035 "scratchy tones". (TIMS 10936, FOCUS 6041)
- Protection of Factory Model ID and Chassis Serial Number. Sometimes during a firmware upgrade the serial number and Factory Model ID were not re-programmed back into the radio. (TIMS 13387)

Compliance None

CSO Instruction CSO's – Please inform all logistics, sales and technical staff, and dealers of these changes

Issuing authority

**Name and position
of issuing officer**

Paul Anderson
Customer Support Engineer - Mobiles

Confidentiality

Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.

**Distribution
Level**

Tait Only

**Document
History**

Original Release

14th May 2003 PRA