

05 A	ADDED HOLE, ALSO RESTRICTED AREA	BRD			23/09/98
04 A	CHANGED HOLE SIZE. UL RATING	BRD			26/08/98
03 A	UPDATED MAYBE NEW CONTACTS	MAJ			2-11-97
02 A	CHANGED ROTATION OF PCB	MAJ			1-8-97
01 A	CORRECTED CONTACTS DUE TO MECH	MAJ			22-7-97
00 A	ORIGINAL	MAJ			1-7-97
REV/ISS	AMENDMENTS	DRAWN	CHKD	D.O.	APVD DATE




TBADMARK  
BADMARK

© TAIT ELECTRONICS

TAIT ORCA SERIES  
FAST CHARGER


IPN: 220-01411-05    ISSUE: 05    ID: 2.SC. 1

PROJECT: ORCA    DESIGNER: BRD    FILE NAME: 141105A    FILE DATE: 23/09/98    NO. SHEETS: 2



© TAIT ELECTRONICS					
TAIT ORCA SERIES TRICKLE CHARGER					
IPN: 220-01411-05		ISSUE: 05		ID: 2.SC. 2	
PROJECT: ORCA	DESIGNER: BRD	FILE NAME: 141105A	FILE DATE: 23/09/98	NO. SHEETS: 2	

REV/ISS	AMENDMENTS	DRAWN	CHKD	D.O.	APVD	DATE



TAIT ELECTRONICS	IPN:	ISS:	ID:	DATE:
	220-01411-05	05	1.TA	29 Sep 1998
CHARGER PCB LAYOUT - TOP SIDE				

