



Technical Note TN-1042-SR

Firmware Release T2035 V3.62 Std

26th August 2005

Applicability

This Technical Note applies only to the Tait T2035 Trunked radio.

1. Introduction

Information

The last full release of T2035 Std firmware was V3.59 (TN-879-SR). **This firmware has now been updated to V3.62**

Detail

The change(s) to the firmware as follows: -

- Incorrect Operation Of SOS Mode - where it was not possible to have a "Non-Stealth" SOS Mode (refer TIMS45034/ FOCUS19859).

Compatibility

Hardware:

Control board IPN **220-01344-05 to -12** with track modification for CTCSS operation

Control board IPN **220-01344-13 or later.**

No longer supported: T2000-A4500 Plug in CTCSS module is not compatible with current and future firmware versions.

Programming Software:

Trunked Programming Application (TPA) **V2.90** or later (DOS no longer supported).

CSO Instruction

CSO's – Please inform all logistics, sales and technical staff and dealers of these changes

Compliance Issues

None

2. Issuing Authority

Name and Position of Issuing Officer

Paul Anderson
Customer Support Engineer - Mobiles

Confidentiality

Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.

Distribution Level

Accredited Service Centre and Tait Only

Document History

Original Release 26th August 2005 PRA