

Errata

The following section is a correction to the HF SSB transceiver reference manual, Codan part number 15-04076 Issue 1, 1997.

The following correction is in Chapter 9, *Link Setup mode— Antenna band or channel control.* The bandset values have been corrected to the values in the following table.

0 4	utpu 2	ts 1	Bandset 1 frequency ranges (MHz)	Bandset 2 frequency ranges (MHz)
L	L	L		< 2
L	L	Н	< 2	2-2.99999
L	Н	L	2-2.99999	3-3.99999
L	Н	Н	3-4.99999	4-5.99999
Н	L	L	5-7.99999	6-8.99999
Н	L	Н	8-12.99999	9–12.99999
Н	Н	L	13-19.99999	13-19.99999
Н	Н	Н	20-30	20-30