



CHANGE REQUEST	
ISSUE B	Y.C
C21 WAS R3 10k	
C/R 23727	10-11-93
ITEM 11 ADDED	
C/R 23747	11-11-93
CAH	
ISSUE C	Y.C
SILKSCREEN CORRECTED	
C/R 23799	10-12-93
CM	13-12-93
ISSUE 2	Y.C
C/R 23930	7-6-94
IC10 WAS 16C452	
CM	6-6-94
ISSUE 3:	
C/R 24227	
PCB WAS ISSUE 2	
CM	10-7-95
ISSUE 4	
SKINNY SRAM's	
ADDED, R16 ADDED.	
C/R 24549	
06-05-96	CAH
ISSUE 5	
08-04826-001 &	
08-04826-002	
VARIANTS ADDED.	
C/R 24870	
L1 TYPE CHANGED	
PCB WAS ISSUE 4	
C/R 24887	
D5 & R17 ADDED	
08-04826-003	
VARIANT ADDED.	
C/R 24934	
24-03-97	CAH
ISSUE 6	
PCB WAS ISSUE 5	
C/R 25001	
29-04-97	CAH
ISSUE 7	
IC14 WAS PCF8582	
NOTE 2 ADDED.	
C/R 25425	
17-06-98	SFD
ISSUE 8:	
PCB WAS ISS -06	
C/R 26281	
27-9-99	SSJ
ISSUE 9:	
R15(56k) DELETED	
C/R 26775	
NJA	9-11-00

NOTE: SECURE TO PCB WITH DOUBLE SIDED FOAM TAPE

NOTES:
 1. ALL DIODES ARE BAW62 OR EQUIVALENT UNLESS OTHERWISE STATED.
 2. FOR WIRE LINKS USE TEFLON WIRE WRAP TF0025 (CPN 66-31012-505)

	IC11	WIRE LINK IC11/PINS 1 & 7	ITEM 10
08-04826-001	TLC32044C	NOT FITTED	90-20525-001
08-04826-002	TLC32047C	FITTED	90-20574-001
08-04826-003	TLC32044C	NOT FITTED	90-20577-001

PCB 07-01618-07

FILE NAME
07\01618_7

	SCALE 2:1		© CODAN PTY LTD, A.C.N. 007 590 605, 1993 DSP MODEM PCB ASSEMBLY	
	DRN.	I.T.		DATE 6-7-93
	CHKD.	CAH		8-7-93
MATERIAL	APPD.	CM	16-12-93	
FINISH	TOLERANCES UNLESS OTHERWISE STATED		DRAWING/DWG No. 08-04826	
	2 PLACES DEC 1 PLACE DEC ANGULAR			
ISS 2 3 4 5 6 7 8 9			SHT 1	