

Addendum

Computer command language

The computer command language displayed on the Remote Control 8570/8571 reflects the software issue that is currently loaded on your transceiver unit (V5.00 software or later). The commands given in *Chapter 6, Computer* are not current.

For the most recent computer command language, you should refer to the *Addendum to HF SSB Transceiver type 9323 User Guide*, (Codan part number 15-04039, from Issue 2, October 1995) or the *Addendum to HF SSB Transceiver type 9360 User Guide*, (Codan part number 15-04053, from Issue 2, August 1995).

If the system has an IPC-500 connected, the remote control console supports SCAN? with SCAN:IPC.

The following commands (from the *Addendum to HF SSB Transceiver type 9323 User Guide* or *Addendum to HF SSB Transceiver type 9360 User Guide*) are not supported in split site systems:

Command...

GPSBEACON=<address>,S

PAGECALL=<address>,"<message>",S

STATUSACK=<address>,"<message>",S

STATUSCALL=<address>,"<message>",S

STATUSTIME=<timeout>

STATUSTIME?

Message...

GPS-POSITION:<channel number>,<address of other station>,<your address>,<time of call>,<GPS position>

NO EXTERNAL UNIT CONNECTED

PAGE-CALL-ACK:<channel number>,<address of other station>,<your address>,<time of call>

PAGE-CALL:<channel number>,<address of other station>,<your address>,<time of call>,"<message>"

STATUS-CALL-ACK:<channel number>,<address of other station>,<your address>,<time of call>,"<message>"

STATUSCALL:<channel number>,<address of other station>,<your address>,<time of call>,"<message>"

STATUSTIME:<timeout>

