



CODAN

## Errata

---

The following section is a correction to the HF SSB Transceiver 9780 Reference Manual, Codan part number 15-04083 Issue 1, June 1997.

## Controlling antenna band and channel outputs

The following correction is in Chapter 4, *Link Setup mode—Controlling antenna band and channel outputs*. The band set values in Table 4-1 have been corrected to the values in the following table.

Outputs			Band set 1 frequency ranges	Band set 2 frequency ranges
4	2	1	(MHz)	(MHz)
L	L	L		<2
L	L	H	<2	2–2.99999
L	H	L	2– 2.99999	3–3.99999
L	H	H	3–4.99999	4–5.99999
H	L	L	5–7.99999	6–8.99999
H	L	H	8–12.99999	9–12.99999
H	H	L	13–19.99999	13–19.99999
H	H	H	20–30	20–30