



MANUAL REVISION
Professional Series Two-Way Radio™
6864110R15-O
HT1250•LS+
Basic Service Manual

This revision outlines changes that have occurred since the printing of your manual. Use this information to supplement your manual. Installation of these changes in earlier equipment is not necessary except as recommended in Motorola Service and Repair Notes (SRNs)

1. On page 3-13, item 16, change Motorola Part Number 0104015J14 to 0104016J92.



This page is intentionally left blank