



Date: 15 February 2000

Subject: New T2000 12 pin flexible loom.



Changes have been carried out to the 12 pin loom, to overcome a possible problem caused by upward pressure from nearby electrolytic capacitors.

The new loom brings the cable out of the other side of the RF board solder in plug, and is about 10mm longer to allow for this.

The new part number for the assembled loom is 219-02005-00.