

Tait Electronics (Aust) Pty Ltd

186 Granite Street
Geebung Qld 4034

Phone: (61) (7) 3865 7799

Fax: (61) (7) 3865 7990

<http://australia.taitworld.com/main/custom>

Product support (61) (7) 3623-9516 (Alan)

or (61) (7) 3623-9547 (Alistair)

alan.prank@tait.com.au

alistair.elrick@tait.com.au

RADIO SOFTWARE AND FIRMWARE SUMMARY

(This issue supersedes all previous issues)

Date: 3 July 2007 Issue: #76

Commercial Information in Strictest Confidence.

Not for information of persons other than direct employees of Tait Dealers.

Tait Communications Ltd

540 Wairakei Road

P O Box 1185

Christchurch New Zealand

Phone 0800 MOBILE / 0800 662453

Fax 03-3582 029

E-mail: helpdesk@tcl.tait.co.nz

<http://support.taitworld.com>

T2000	DOS s/w	WIN s/w		Firmware	
T2010 Old radio 1992/3	2.04	X		1.04	
T2015 Old radio 1992/3	1.05	X		1.02	
T201X All other 2010 & 2015	1.40	3.01	B	3.05	B
T2020 S1	2.54	3.01	B	4.09	B
T2020 S1.5	2.54	3.01	B	5.29	B
T2020 S2 100 CH Radios	X	3.01	B	5.66	T
T2020 S2 1200 CH Radios	X	3.01	B	7.23	S
T2030 S1	1.61	X		1.17	
T2030 S2	X	3.01	B	3.43	K
T2030 S2 GPS	X	3.01	B	4.25	P
T2035 S1	1.61	X		2.02	
T2035 S2	X	3.01	B	3.66	L
T2035 S2 GPS	X	3.01	B	4.25	Q
T2040 S1	2.77	X		4.12	
T2040 S1.5	2.77	X		4.32	
T2040 S2	X	3.01	B	5.79	M
T2040 S2 GPS	X	3.01	B	6.24	R
T2050 Use 2020/2040 S1		X		4.09	

TM8000	DOS s/w	WIN s/w		Firmware	
TM81xx Programming	X	3.02	D	2.13	D
TM8xxx Calibration	X	4.03	H	2.13/4.02	D
TM8250-55 Programming	X	4.01	H	4.02	H
TM8260 Programming	X	4.01	H	4.02	H

TB8000	DOS s/w	WIN s/w		Firmware	
TB8100 Reciter	X	3.05	A	3.05	A
TB8100 PA	X	3.05	A	3.05	A
TB8100 PMU	X	3.05	A	2.08	A
TB8100 Calibration	X	3.06	A	2.08/3.05	A

TB9100	DOS s/w	WIN s/w		Firmware	
TB9100 Programming	X	3.05	E	3.05	E
TB9100 Calibration	X	3.06	E	3.05	E

TM9100/TP9100	DOS s/w	WIN s/w		Firmware	
TM9100 - TP9100 Programming	X	1.19		3.08	U
TM9100 - TP9100 Calibration	X	1.06		3.08	
TM9100 HHCH	X	1.19		3.05	

T700	DOS s/w	WIN s/w		Firmware	
T700 SIMPLEX & DUPLEX	3.10	X		3.09	
T700 LOW CURRENT	3.07	X		3.20	
T700 TRUNKING	TOPS 3.02	X		3.08	
T700 CNV WITH AE096 BOARD	3.00	X		3.30	

T3000	DOS s/w	WIN s/w		Firmware	
T3010 STANDARD	1.02	X		1.05	
T3010 ENHANCED	2.14	X		2.04	
T3020 S1	2.01	X		1.09	
T3020 S2	2.01	X		1.18	
T3030 S1	2.28	X		1.01	
T3030 S2	2.28	X		2.17	
T3035 S1	2.28	X		1.01	
T3035 S2	2.28	X		2.22	
T3040 S1	1.03	X		1.06	
T3040 S2	2.28	X		3.16	
T3000 CALIBRATION	2.12	X		X	
ORCA/T5000 CHARGER	X	X		3.09	

T5000	DOS s/w	WIN s/w		Firmware	
ORCA "E" SERIES CNV	X	4.13	O	1.27	
ORCA "E" SERIES TRK	X	4.13	O	3.15	
ORCA T5010 CNV	X	4.13	O	2.18	F
ORCA T5015 CNV	X	4.13	O	2.18	F
ORCA T5020 CNV	X	4.13	O	2.18	F
ORCA T5030 TRK	X	4.13	O	4.33	G
ORCA T5035 TRK	X	4.13	O	4.33	G
ORCA T5040 TRK	X	4.13	O	4.33	G
ORCA CALIBRATION SOFTWARE	X	4.13	O	N/A	

TB7100	DOS s/w	WIN s/w		Firmware	
TB7100 Programming	X	1.14	C	2.13	C
TB7100 Calibration	X	1.11	C	2.13	C

T800	DOS s/w	WIN s/w		Firmware	
T800 S1 & S2	X	4.30		1.01 (S2)	
T800 S1	2.12	X		X	

Please refer to the following Tech Notes for full details of the Software and Firmware.

- A=TN-1265-SR in Service Package
- B=TN-1228-SR
- C=TN-1201-SR
- D=TN-1221b-SR
- E=TN-1246-SR in Service package
- F=TN-1241-SR
- G=TN-1242-SR
- H=TN-1258d-SR
- K=TN-1225-SR
- L=TN-1226-SR
- M=TN-1227-SR
- O=TN-1240-SR
- P=TN-1231-SR
- Q=TN-1232-SR
- R=TN-1233-SR
- S=TN-1224a-SR
- T=TN-1223-SR
- U=TN-1250-SR (included with the PGM)

Please Note!
Before changing Firmware in T5000, TM8000 and TB7100 radios, we advise you read the radio Calibration and Data files and save them. This can eliminate having to re-calibrate the radio or recreate the Database file after the upgrade.