



Technical Support

TECHNICAL NOTE

Technical Note TN-824 Release of TB8100 Service Kit version 1.03

11 December 2003

Applicability This Technical Note applies to all TB8100 Base Stations.

1. Introduction

Information Version 1.03 of the TB8100 Service kit has now been released and supercedes all previous versions.

The new features included in this version are as follows:

Support for Chinese, French, and Spanish

The TB8100 Service Kit and Alarm Center are now available in Chinese, French, and Spanish. The online Help is also translated.

2. Issues Fixed

Service Kit version 1.03 has fixed a problem in the display of the New Connections and Editing Connections screens of version 1.02.

3 Upgrading to Service Kit Version 1.03

If your PC already has the Service Kit installed, you must remove the old version before installing the new. Begin the installation in the usual way. In the Welcome screen, select Remove to remove all installed components. Then begin the installation again.

4 Compatibility

Service Kit version 1.03 is fully compatible with all base stations fitted with firmware version 1.01. Configurations that were created with Service Kit version 1.01 and later do not need to be converted.

5. Issuing Authority

Name and Position of Issuing Officer

Rob Ottaway
Technical Support Team Leader Infrastructure.

Confidentiality

Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.

Distribution Level

Tait Only

Document History

Original Release 11 December 2003