

# Technical Note TN-633 **T2020 Factory Software Upgrades** 5 September 2000

Applicability

This Technical Note only applies to the T2020 radio units being assembled on the T2000 production line.

### 1. T2020 Programming Software.

Details

The last FULL release T2020 programming software to be used in production was V2.40. This software has been surpassed by V2.49 T2020 Programming software.

The main changes to note are:

- Supports 8 digit serial numbering
- Will program the radio firmware required to be used with the SST flash.
- Various new frequency band additions.
- Various bug fixes.

The new software will be required to program radios from **Job number 215026** 

#### Please Note:

- Kan Ban stock will not be upgraded unless otherwise requested by the CSO.
- The programming software is available to download off the Technical Issues Database under the Software section.

Telephone: +64–3–358–3399 Facsimile: +64–3–358–3903

## 2. T2020 Radio Firmware.

Details

The last FULL release T2020 programming software to be used in production was V5.20. This software has been surpassed by V5.47 T2020 Radio Firmware.

The main changes to note are:

- SST / ST Flash capable
- E1 HC11 micro capable
- Various bug fixes and enhancements

The new T2020 Radio Firmware will be placed is radios from **Job Number 215026.** 

#### **Please Note:**

- Kan Ban stock will not be upgraded, unless otherwise requested by the CSO.
- The radio firmware is available to download off the Technical Issues Database under the Software section.

**CSO's:** Please inform all logistics, sales, technical staff and dealers of these changes.

### 3. Issuing authority

Name and position	Barry Crates
of issuing officer	T2000 & T3000 Customer Support Engineer