

TECHNICAL NOTE TN-1168-SR 5030, 5035, 5040 Firmware Upgrade to 4.32

& TOP-TPA Upgrade to 4.12.00

12 May 2006

Applicability

This Technical Note applies to the firmware utilised in the Tait Orca 5030, 5035, and 5040 MPT 1327 Trunked radios.

It also applies to the TOP Trunked Programming Application v4.12.00 used to read / program radio personality files.

1. Introduction

The Orca Trunked Firmware v4.32 has been released to manufacturing to replace the previous firmware (v4.31) being installed in Tait Orca 5030, 5035, and 5040 MPT 1327 products.

Version 4.32 firmware was first implemented in an Orca TOP-XXXX-B0, radio serial number XXXXXXX, job XXXXXXX, on XXXXX 2006. (These details will be inserted and the Technical Note reissued when the information is available).

What does this work with?

This Firmware is compatible only with the TOP Trunked Programming Application (TOP-TPA) v4.12.00 or later.

The TOP-TPA v4.12.00 is available on the Tait Portables Programming Utilities (TPPU) v4.12.00 CD-ROM from the Tait Software Issuing Authority as IPN 406-00003-12, or for download from support.taitworld.com under "Portables – Orca / T3000" \rightarrow "Programming Software".

2. Changes

What has been resolved in this release?

Firmware version 4.32 resolves the following issues in the Orca 5030, 5035, and 5040:

- The 'Menu Button Initiates Call' option would not initiate calls from the call queue. (Raised as TIMS 51036).
- FOCUS 24034: Resolved issue whereby if the system was utilising control channel reversion, then a group call was initiated, the receiving radio(s) would not un-mute until the user had pressed PTT. (Raised as TIMS 53386).

Changes to the TOP-TPA v4.12.00

The TOP Trunked Programming Application v4.12.00 resolves the following issues:

• FOCUS 24971: Resolved issue whereby specific DCS tones, for use in conventional mode, would not be correctly saved (or read back from the radio). (Raised as TIMS 55372).

Telephone:+64-3-357-9991

TN-1168-SR_5000_4_32_&_TPA_4_12_00.doc

Date of Print: 12/05/06

Compliance Issues	None
CSO Instruction	CSO's – Please inform all logistics, sales and technical staff of these changes.

3. Issuing Authority

Name and Position of Issuing Officer	Tim Lummis Technical Support Engineer		
Confidentiality	Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.		
Distribution Level	Associate		
Document History	Original Release	12 May 2006	TPL

Telephone:+64-3-357-9991