

Technical Note TN-680

Orca Trunked Programming Software V 3.2.0

13th August 2001

Applicability

This Technical Note applies to the Tait Orca trunked series. Elan, Excel, 5030, 5035 and 5040.

1. Information.

This commercial upgrade 3.2.0 was released to fix three issues, based on 3.1.0. Firstly a radio unit number restriction problem. Secondly an error in reading a previous database and thirdly a network identity code limitation.

Changes made are:

- An error was occuring when reading database versions previous to 1.07 the latest database for the original Orca radios. A default has been entered for MPT Dynamic regrouping, the ST network parameter and the multiple registration fields. See TID 2098
- The network identity code was being read back incorrectly. The fault was that only 6 bits of the number were being used instead of 7. See TID 2217
- The maximum radio unit number was being incorrectly set to the value of the range for individual calls. This has now been set to the maximum individual number in the fleet as on the fleet identity form. See TID 2273

2. Issuing authority

Name and positionStephen PavettOf issuing officerCustomer Support Engineer

Tait Electronics Limited PO Box 1645, Christchurch, New Zealand Telephone: +64–3–358–3399 Facsimile: +64–3–358–3903