



---

## Technical Note TN-675

# Firmware upgrade for Trunked Slim TOP 4.06

2<sup>nd</sup> July 2001

---

### Applicability

This Technical Note applies to all trunked slim TOP portables (5030, 5035 and 5040).

---

## 1. Information.

This firmware 4.06 primarily is to correct the operation of unanswered call queuing.

Other changes made to this version contains the following:

- Changed operation of answered call queuing to not send ACKB command.
- Changed shut down threshold for battery voltage.
- Contrast can be reset by holding down the function key 2 at power-up.

Compatible with Orca Trunking Programming Application V3.1.0 and Orca Calibration Application V3.1.0. (**TPU version 2.1**)

Changes take effect from the following S/N: 14115798 19/6/01.

## 2. Issuing authority

<b>Name and position Of issuing officer</b>	Stephen Pavett Customer Support Engineer
---	---