



Technical Note TN-681

Orca Conventional Programming Software V 3.2.0

23rd July 2001

Applicability

This Technical Note applies to all conventional TOP portables (Elan, Excel, Eclipse, 5010 and 5020).

1. Information.

This firmware 4.06 primarily is to correct the operation of unanswered call queuing.

Other changes made to this version contains the following:

- Changed operation of answered call queuing to not send ACKB command.
- Changed shut down threshold for battery voltage.
- Contrast can be reset by holding down the function key 2 at power-up.

2. Issuing authority

**Name and position
Of issuing officer**

Stephen Pavett
Customer Support Engineer